




INSTALLATION INSTRUCTIONS (SHEET 1)



BOTTOM VIEW

ASSEMBLY STEPS:

1. ATTACH SC-1000-PB TO 4X FLOOR ANCHOR STUDS. M8 OR 5/16" STUD SIZE RECOMMENDED. MOUNTING HARDWARE IS NOT INCLUDED.

| | | | |
|-------------------------------|-------------------|---|---|
| DWG. NO. SC-1000-PB | REV. C | TITLE SELF CHECK-OUT, PEDESTAL MOUNTED, BOLT DOWN |  SHEET 1 OF 2 |
| DRAWN S. YANG | DATE 7/10/2023 | | |

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF HAVIS, INC. AND REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF HAVIS, INC. IS PROHIBITED.



CUSTOMER INSTRUCTIONS

INSTALLATION INSTRUCTIONS

SHEET 2

(SOME PARTS HIDDEN FOR CLARITY)

- TOOLS LIST:
 1. 3MM HEX WRENCH OR BIT WITH DRIVER
 2. #1 PHILLIPS SCREW DRIVER



- ASSEMBLY STEPS:
2. LOOSEN 2X SET SCREWS.
 3. HOLD DISPLAY ATTACHMENT BRACKET AT DESIRED HEIGHT.
 4. TIGHTEN 2X SET SCREWS.
 5. ATTACH DISPLAY WITH 4X M4 X 10MM LONG PHILLIPS SCREWS.
 6. PLACE PRINTER INTO SC-1000-CF UNIT. 4X SCREWS CAN BE LOOSENED TO ADJUST PRINTER BRACKET (SEE DETAIL B).
(OPTIONAL) DUAL LOCK (2 STRIPS INCLUDED) CAN BE USED UNDER THE PRINTER TO HOLD IT IN PLACE IF DESIRED.

| | | | |
|------------------------|-------------------|--|---|
| DWG. NO. SC-1000-CF | REV. C | TITLE SC-1000, SELF CHECK-OUT,COUNTER TOP, FIXED BASE |  SHEET 2 OF 2 |
| DRAWN S. YANG | DATE 3/27/2023 | | |

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF HAVIS, INC. AND REPRODUCTION IN PART OR IN WHOLE WITHOUT THE WRITTEN PERMISSION OF HAVIS, INC. IS PROHIBITED.

CUSTOMER INSTRUCTIONS